

**Traveler Title:**

Booster Correction Multipole Magnet Assembly

**Specification No:**

5520-TR-333819

**Revision:**

J

**DR No:**

4534

**Step No:**

7.10

**Drawing No:**

ME-445311

**Routing Form No:****Serial No:**

BMA064

**Rework ID:**

0

**Discrepancy Description:**

Traveler instructs to Measure the following windings parameters.  
The D.C. resistance limit for the Skew Quad circuit is 1300 milli ohms - 1400milli ohms.  
Actual Skew Quad circuit D.C resistance measured 1221 milli ohms.

**Originator:**

Dennis Gaw

**Date:**

7/24/2008 10:20:48 AM

**Cause of Nonconformance:**

Five of the eight C1 coils used a different type of conductor than the "typical" coil. The layer 5 (skew quad) resistance for these coils is around 140 m-ohms, which is about 30 m-ohms less than the nominal value. The total effect on the skew quad circuit is about 150 m-ohms, which would put the total resistance back into the limit.

**Responsible Authority:**

Jamie Blowers

**Date:**

7/24/2008 10:20:48 AM

**Disposition:**

Accept magnet as-is. This is a known issue, and since each magnet is powered individually this will not pose an operational problem.

Disposition verify notes: Assembly has proceeded with this magnet.

**Responsible Authority:**

Jamie Blowers

**Date:**

7/24/2008 4:45:20 PM

**Corrective Action to Prevent Recurrence:**

None. This deviation was pre-approved by Fermilab.

Disposition verify notes: None.

**Responsible Authority:**

Jamie Blowers

**Date:**

7/24/2008 4:45:20 PM

**Corrective Action/Disposition Verified By:**

Dennis Gaw

**Date:**

8/19/2008 2:05:15 PM

Will Configuration be affected?:

☐ YES

☒ NO

**Identified problem area:**

☐ Material

☐ Manpower

☐ Method

☐ Machine

☒ Measurement

**Reviewed By:**

Bob Jensen

**Date:**

8/20/2008 8:42:13 AM